

	Activity Name	Quantity (done/req./spare)	Responsibility
1	Detector Constuction		
2	Proton Segments		
3	hut polishing (1)	3/4/0	Commerical
4	BeO rods (2)	4/4/2	JA
5	rolled Indium sheet		
6	elastomer det rings (148)	12/128/32	
7	Electronics		
8	Preamps (50)	50/64/36	AM
9	Motherboards (4)	1/4/1	HPM
10	internal cable repair (1)	3/4/0	
11	FO I/O board (1)	1/1/1	
12	FO temp sensors (4)	2/4/2	
13	FO transmitters (8)	2/8/2	
14	FO recievers (6)	87/64/29	
15	FO circular board mod (5)	0/4/1	
16	HV system		
17	HV cable connectors (2)	2/4/0	
18	Fix noise (from DVM monitoring)		
19	Revise HV internal wiring		
20	Interlock System		
21	verify vacuum operation		PP